

AD-A041 282

LEEDS AND NORTHRUP CO NORTH WALES PA  
ENZYME ALARM INSTRUMENTATION STUDIES.(U)  
OCT 76 W MCADAM, R M TAYLOR

F/G 15/2

UNCLASSIFIED

ED-CR-76106

DAAA15-76-C-0113  
NL

1 OF 1

AD  
A041282



END

DATE  
FILMED

7-77





ADA 041 282

AD

EDGEWOOD ARSENAL CONTRACTOR REPORT

ED-CR-76106

ENZYME ALARM INSTRUMENTATION STUDIES

FIRST QUARTERLY REPORT

By

W. McAdam

R. M. Taylor

October 1976

LEEDS & NORTHRUP COMPANY  
North Wales, PA 19454

Contract DAAA 15-76-C-0113 *new*



DEPARTMENT OF THE ARMY  
Headquarters, Edgewood Arsenal  
Aberdeen Proving Ground, Maryland 21010



Approved for public release, distribution unlimited



DDC FILE COPY

Disclaimer

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

Disposition

Destroy this report when it is no longer needed. Do not return it to the originator.

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER ED-CR-76106	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) ENZYME ALARM INSTRUMENTATION STUDIES		5. TYPE OF REPORT & PERIOD COVERED Quarterly Progress, May 1976 thru August '76
7. AUTHOR(s) W. McAdam R. M. Taylor		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS Leeds & Northrup Company North Wales, PA 19454		8. CONTRACT OR GRANT NUMBER(s) Contract DAAA-76-C-0113
11. CONTROLLING OFFICE NAME AND ADDRESS Commander, Edgewood Arsenal Attn: SAREA-TS-R Aberdeen Proving Ground, MD 21010		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Commander, Edgewood Arsenal ATTN: SAREA-DE-DDA Aberdeen Proving Ground, MD 21010 (Andrew Davis, Project Officer 671-2882)		12. REPORT DATE October 1976
		13. NUMBER OF PAGES 15
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
16. DISTRIBUTION STATEMENT (of this Report)  Approved for public release; distribution unlimited		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE NA
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)		
Butyrlthiocholine iodide Electrochemical alarm Fieldable enzyme alarm Cholinesterase Thermostated alarm Foamed insulation Controlled potential Interference compensation Alarm fabrication		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number)		
Polarographic-type electrochemical enzyme alarms were designed and engineered to automatically detect C-agents in the field. The target specifications include lower power consumption, small size, light weight, and operating capability from -40°F to +120°F. Interference compensation and controlled potential circuitry developed under Edgewood Arsenal Contract DAAA15-75-C-0134 were included. Fabrication and testing of three electro-		

DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED


SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

20. (Abstract cont'd)

chemical cells were successfully completed. Fabrication of component parts for three alarm systems is nearly complete with assembly underway.



UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



## PREFACE

The experimental and development work described in this report was authorized under Contract No. DAAA 15-76-C-0113 entitled "Enzyme Alarm Instrumentation Studies". It was performed by the Leeds & Northrup Company for the U. S. Army Edgewood Arsenal.

This report documents the part of the work performed during the period May through August, 1976. The work is continuing toward the objective of three operating prototype instruments embodying the results of the development.

Reproduction of this document in whole or in part is prohibited except with permission of the Commander, Edgewood Arsenal, Attn: SAREA-TS-R, Aberdeen Proving Ground, Maryland 21010; however, DDC and National Technical Information Service are authorized to reproduce the document for United States Government purposes.

The use of trade names in this report does not constitute an official endorsement or approval of such commercial hardware or software. This report may not be cited for purposes of advertisement.

Form 100-1 (Rev. 1-60)

1. NAME (Last, first, middle initial)  
2. GRADE OR POSITION  
3. ORGANIZATION  
4. ADDRESS  
5. CITY  
6. STATE  
7. ZIP CODE  
8. PHONE NUMBER  
9. DATE  
10. SIGNATURE  
11. TITLE  
12. ORGANIZATION  
13. ADDRESS  
14. CITY  
15. STATE  
16. ZIP CODE  
17. PHONE NUMBER  
18. DATE  
19. SIGNATURE  
20. TITLE  
21. ORGANIZATION  
22. ADDRESS  
23. CITY  
24. STATE  
25. ZIP CODE  
26. PHONE NUMBER  
27. DATE  
28. SIGNATURE  
29. TITLE  
30. ORGANIZATION  
31. ADDRESS  
32. CITY  
33. STATE  
34. ZIP CODE  
35. PHONE NUMBER  
36. DATE  
37. SIGNATURE  
38. TITLE  
39. ORGANIZATION  
40. ADDRESS  
41. CITY  
42. STATE  
43. ZIP CODE  
44. PHONE NUMBER  
45. DATE  
46. SIGNATURE  
47. TITLE  
48. ORGANIZATION  
49. ADDRESS  
50. CITY  
51. STATE  
52. ZIP CODE  
53. PHONE NUMBER  
54. DATE  
55. SIGNATURE  
56. TITLE  
57. ORGANIZATION  
58. ADDRESS  
59. CITY  
60. STATE  
61. ZIP CODE  
62. PHONE NUMBER  
63. DATE  
64. SIGNATURE  
65. TITLE  
66. ORGANIZATION  
67. ADDRESS  
68. CITY  
69. STATE  
70. ZIP CODE  
71. PHONE NUMBER  
72. DATE  
73. SIGNATURE  
74. TITLE  
75. ORGANIZATION  
76. ADDRESS  
77. CITY  
78. STATE  
79. ZIP CODE  
80. PHONE NUMBER  
81. DATE  
82. SIGNATURE  
83. TITLE  
84. ORGANIZATION  
85. ADDRESS  
86. CITY  
87. STATE  
88. ZIP CODE  
89. PHONE NUMBER  
90. DATE  
91. SIGNATURE  
92. TITLE  
93. ORGANIZATION  
94. ADDRESS  
95. CITY  
96. STATE  
97. ZIP CODE  
98. PHONE NUMBER  
99. DATE  
100. SIGNATURE  
101. TITLE  
102. ORGANIZATION  
103. ADDRESS  
104. CITY  
105. STATE  
106. ZIP CODE  
107. PHONE NUMBER  
108. DATE  
109. SIGNATURE  
110. TITLE  
111. ORGANIZATION  
112. ADDRESS  
113. CITY  
114. STATE  
115. ZIP CODE  
116. PHONE NUMBER  
117. DATE  
118. SIGNATURE  
119. TITLE  
120. ORGANIZATION  
121. ADDRESS  
122. CITY  
123. STATE  
124. ZIP CODE  
125. PHONE NUMBER  
126. DATE  
127. SIGNATURE  
128. TITLE  
129. ORGANIZATION  
130. ADDRESS  
131. CITY  
132. STATE  
133. ZIP CODE  
134. PHONE NUMBER  
135. DATE  
136. SIGNATURE  
137. TITLE  
138. ORGANIZATION  
139. ADDRESS  
140. CITY  
141. STATE  
142. ZIP CODE  
143. PHONE NUMBER  
144. DATE  
145. SIGNATURE  
146. TITLE  
147. ORGANIZATION  
148. ADDRESS  
149. CITY  
150. STATE  
151. ZIP CODE  
152. PHONE NUMBER  
153. DATE  
154. SIGNATURE  
155. TITLE  
156. ORGANIZATION  
157. ADDRESS  
158. CITY  
159. STATE  
160. ZIP CODE  
161. PHONE NUMBER  
162. DATE  
163. SIGNATURE  
164. TITLE  
165. ORGANIZATION  
166. ADDRESS  
167. CITY  
168. STATE  
169. ZIP CODE  
170. PHONE NUMBER  
171. DATE  
172. SIGNATURE  
173. TITLE  
174. ORGANIZATION  
175. ADDRESS  
176. CITY  
177. STATE  
178. ZIP CODE  
179. PHONE NUMBER  
180. DATE  
181. SIGNATURE  
182. TITLE  
183. ORGANIZATION  
184. ADDRESS  
185. CITY  
186. STATE  
187. ZIP CODE  
188. PHONE NUMBER  
189. DATE  
190. SIGNATURE  
191. TITLE  
192. ORGANIZATION  
193. ADDRESS  
194. CITY  
195. STATE  
196. ZIP CODE  
197. PHONE NUMBER  
198. DATE  
199. SIGNATURE  
200. TITLE  
201. ORGANIZATION  
202. ADDRESS  
203. CITY  
204. STATE  
205. ZIP CODE  
206. PHONE NUMBER  
207. DATE  
208. SIGNATURE  
209. TITLE  
210. ORGANIZATION  
211. ADDRESS  
212. CITY  
213. STATE  
214. ZIP CODE  
215. PHONE NUMBER  
216. DATE  
217. SIGNATURE  
218. TITLE  
219. ORGANIZATION  
220. ADDRESS  
221. CITY  
222. STATE  
223. ZIP CODE  
224. PHONE NUMBER  
225. DATE  
226. SIGNATURE  
227. TITLE  
228. ORGANIZATION  
229. ADDRESS  
230. CITY  
231. STATE  
232. ZIP CODE  
233. PHONE NUMBER  
234. DATE  
235. SIGNATURE  
236. TITLE  
237. ORGANIZATION  
238. ADDRESS  
239. CITY  
240. STATE  
241. ZIP CODE  
242. PHONE NUMBER  
243. DATE  
244. SIGNATURE  
245. TITLE  
246. ORGANIZATION  
247. ADDRESS  
248. CITY  
249. STATE  
250. ZIP CODE  
251. PHONE NUMBER  
252. DATE  
253. SIGNATURE  
254. TITLE  
255. ORGANIZATION  
256. ADDRESS  
257. CITY  
258. STATE  
259. ZIP CODE  
260. PHONE NUMBER  
261. DATE  
262. SIGNATURE  
263. TITLE  
264. ORGANIZATION  
265. ADDRESS  
266. CITY  
267. STATE  
268. ZIP CODE  
269. PHONE NUMBER  
270. DATE  
271. SIGNATURE  
272. TITLE  
273. ORGANIZATION  
274. ADDRESS  
275. CITY  
276. STATE  
277. ZIP CODE  
278. PHONE NUMBER  
279. DATE  
280. SIGNATURE  
281. TITLE  
282. ORGANIZATION  
283. ADDRESS  
284. CITY  
285. STATE  
286. ZIP CODE  
287. PHONE NUMBER  
288. DATE  
289. SIGNATURE  
290. TITLE  
291. ORGANIZATION  
292. ADDRESS  
293. CITY  
294. STATE  
295. ZIP CODE  
296. PHONE NUMBER  
297. DATE  
298. SIGNATURE  
299. TITLE  
300. ORGANIZATION  
301. ADDRESS  
302. CITY  
303. STATE  
304. ZIP CODE  
305. PHONE NUMBER  
306. DATE  
307. SIGNATURE  
308. TITLE  
309. ORGANIZATION  
310. ADDRESS  
311. CITY  
312. STATE  
313. ZIP CODE  
314. PHONE NUMBER  
315. DATE  
316. SIGNATURE  
317. TITLE  
318. ORGANIZATION  
319. ADDRESS  
320. CITY  
321. STATE  
322. ZIP CODE  
323. PHONE NUMBER  
324. DATE  
325. SIGNATURE  
326. TITLE  
327. ORGANIZATION  
328. ADDRESS  
329. CITY  
330. STATE  
331. ZIP CODE  
332. PHONE NUMBER  
333. DATE  
334. SIGNATURE  
335. TITLE  
336. ORGANIZATION  
337. ADDRESS  
338. CITY  
339. STATE  
340. ZIP CODE  
341. PHONE NUMBER  
342. DATE  
343. SIGNATURE  
344. TITLE  
345. ORGANIZATION  
346. ADDRESS  
347. CITY  
348. STATE  
349. ZIP CODE  
350. PHONE NUMBER  
351. DATE  
352. SIGNATURE  
353. TITLE  
354. ORGANIZATION  
355. ADDRESS  
356. CITY  
357. STATE  
358. ZIP CODE  
359. PHONE NUMBER  
360. DATE  
361. SIGNATURE  
362. TITLE  
363. ORGANIZATION  
364. ADDRESS  
365. CITY  
366. STATE  
367. ZIP CODE  
368. PHONE NUMBER  
369. DATE  
370. SIGNATURE  
371. TITLE  
372. ORGANIZATION  
373. ADDRESS  
374. CITY  
375. STATE  
376. ZIP CODE  
377. PHONE NUMBER  
378. DATE  
379. SIGNATURE  
380. TITLE  
381. ORGANIZATION  
382. ADDRESS  
383. CITY  
384. STATE  
385. ZIP CODE  
386. PHONE NUMBER  
387. DATE  
388. SIGNATURE  
389. TITLE  
390. ORGANIZATION  
391. ADDRESS  
392. CITY  
393. STATE  
394. ZIP CODE  
395. PHONE NUMBER  
396. DATE  
397. SIGNATURE  
398. TITLE  
399. ORGANIZATION  
400. ADDRESS  
401. CITY  
402. STATE  
403. ZIP CODE  
404. PHONE NUMBER  
405. DATE  
406. SIGNATURE  
407. TITLE  
408. ORGANIZATION  
409. ADDRESS  
410. CITY  
411. STATE  
412. ZIP CODE  
413. PHONE NUMBER  
414. DATE  
415. SIGNATURE  
416. TITLE  
417. ORGANIZATION  
418. ADDRESS  
419. CITY  
420. STATE  
421. ZIP CODE  
422. PHONE NUMBER  
423. DATE  
424. SIGNATURE  
425. TITLE  
426. ORGANIZATION  
427. ADDRESS  
428. CITY  
429. STATE  
430. ZIP CODE  
431. PHONE NUMBER  
432. DATE  
433. SIGNATURE  
434. TITLE  
435. ORGANIZATION  
436. ADDRESS  
437. CITY  
438. STATE  
439. ZIP CODE  
440. PHONE NUMBER  
441. DATE  
442. SIGNATURE  
443. TITLE  
444. ORGANIZATION  
445. ADDRESS  
446. CITY  
447. STATE  
448. ZIP CODE  
449. PHONE NUMBER  
450. DATE  
451. SIGNATURE  
452. TITLE  
453. ORGANIZATION  
454. ADDRESS  
455. CITY  
456. STATE  
457. ZIP CODE  
458. PHONE NUMBER  
459. DATE  
460. SIGNATURE  
461. TITLE  
462. ORGANIZATION  
463. ADDRESS  
464. CITY  
465. STATE  
466. ZIP CODE  
467. PHONE NUMBER  
468. DATE  
469. SIGNATURE  
470. TITLE  
471. ORGANIZATION  
472. ADDRESS  
473. CITY  
474. STATE  
475. ZIP CODE  
476. PHONE NUMBER  
477. DATE  
478. SIGNATURE  
479. TITLE  
480. ORGANIZATION  
481. ADDRESS  
482. CITY  
483. STATE  
484. ZIP CODE  
485. PHONE NUMBER  
486. DATE  
487. SIGNATURE  
488. TITLE  
489. ORGANIZATION  
490. ADDRESS  
491. CITY  
492. STATE  
493. ZIP CODE  
494. PHONE NUMBER  
495. DATE  
496. SIGNATURE  
497. TITLE  
498. ORGANIZATION  
499. ADDRESS  
500. CITY  
501. STATE  
502. ZIP CODE  
503. PHONE NUMBER  
504. DATE  
505. SIGNATURE  
506. TITLE  
507. ORGANIZATION  
508. ADDRESS  
509. CITY  
510. STATE  
511. ZIP CODE  
512. PHONE NUMBER  
513. DATE  
514. SIGNATURE  
515. TITLE  
516. ORGANIZATION  
517. ADDRESS  
518. CITY  
519. STATE  
520. ZIP CODE  
521. PHONE NUMBER  
522. DATE  
523. SIGNATURE  
524. TITLE  
525. ORGANIZATION  
526. ADDRESS  
527. CITY  
528. STATE  
529. ZIP CODE  
530. PHONE NUMBER  
531. DATE  
532. SIGNATURE  
533. TITLE  
534. ORGANIZATION  
535. ADDRESS  
536. CITY  
537. STATE  
538. ZIP CODE  
539. PHONE NUMBER  
540. DATE  
541. SIGNATURE  
542. TITLE  
543. ORGANIZATION  
544. ADDRESS  
545. CITY  
546. STATE  
547. ZIP CODE  
548. PHONE NUMBER  
549. DATE  
550. SIGNATURE  
551. TITLE  
552. ORGANIZATION  
553. ADDRESS  
554. CITY  
555. STATE  
556. ZIP CODE  
557. PHONE NUMBER  
558. DATE  
559. SIGNATURE  
560. TITLE  
561

## TABLE OF CONTENTS

	<u>Page</u>
1. BACKGROUND AND INTRODUCTION . . . . .	5
2. EXPERIMENTAL RESULTS . . . . .	8
3. FURTHER WORK . . . . .	12
DISTRIBUTION LIST . . . . .	13



## ENZYME ALARM INSTRUMENTATION STUDIES

### 1. BACKGROUND AND INTRODUCTION

For the past several years Edgewood Arsenal has been conducting studies on an electrochemical enzyme alarm system for the detection of chemical agents. This alarm monitors the extent of the enzyme-catalyzed hydrolysis of butyrylthiocholine iodide. In April 1975, Leeds & Northrup Company was awarded Contract DAAA 15-75-C-0134 to study means for suppressing alarm interferences with improved-time-response characteristics.

The present contract, for which this report is made, was awarded to Leeds & Northrup Company on May 13, 1976 to provide alarm instruments for limited field testing based on the improvements made under the aforementioned contract. The specific goals of this project are:

- (a) Optimize hardware and circuit design of the enzyme alarm, within the time constraints imposed by goal (c).
- (b) Fabricate and assemble three enzyme alarm instruments for limited field testing by Edgewood Arsenal.
- (c) Deliver the three instruments to Edgewood Arsenal by November 1, 1976.

#### 1.1 Project Plan

This project logically divides into three phases - Optimization and Design, Fabrication and Assembly, and Test and Evaluation.

##### 1.1.1 Optimization and Design

This phase basically comprised hardware design using a combination of some approaches which had been suggested and verified by Edgewood Arsenal and the improvements resulting from Contract DAAA 15-75-C-0134. Optimization for the purposes of this contract consisted of defining the specific overall and component designs which were most suitable for fabrication, assembly, and testing within the contractual time constraints, and which could be produced with reasonable ease for additional instruments. Minimum-cost parts fabrication with manufacturing tooling was, however, not an important criterion for the designs. The major part of the design either made direct use of approaches which had been verified by Edgewood Arsenal in hand-made models,

or adapted such concepts with minimal modifications for ease in fabrication. Since testing time is severely limited under the contractual time constraints, further optimization of the Edgewood Arsenal concepts was not to be attempted.

Those parts of the alarms based on the Leeds & Northrup improvements were designed using the data available in the final report on Contract CAAA 15-75-C-0134. These latter designs were limited to the electrochemical cell and parts of the associated electronic circuitry.

#### 1.1.2 Fabrication and Assembly

This phase consisted entirely of Model Shop fabrication of alarm parts, expediting and procurement of purchased components, and assembly of parts and components into finished alarms by engineers and technicians. This phase constitutes by far the greatest expenditure of manpower on the project, and is the most critical from the standpoint of meeting the schedule requirements.

#### 1.1.3 Test and Evaluation

This phase is divided into two parts -- tests of the first model electrochemical cell of the new design, and overall tests of the assembled enzyme alarms. The first tests of the new design cell were necessary to confirm its satisfactory operation as a basis for proceeding with construction of the alarms. These tests were accomplished during August, and are described in section 2 of this report. Overall tests of the assembled alarms will be conducted during the latter part of September prior to shipment. These will include both performance and environmental testing, and the results will be included in the Project Final Report.

Evaluation will include consideration of the alarm design as well as its performance. Final recommendations will be based in part on the evaluation.

### 1.2 Problems

All of the electrochemical problems associated with the design of these enzyme alarms were dealt with successfully under the previous study contract DAAA 15-75-C-0134. The problems encountered in the present work were related to adaptation of the Edgewood Arsenal concepts to designs for practical fabrication, detailed design of new parts not included in the Edgewood Arsenal concepts, and procurement of commercial components on the schedule required to meet the delivery commitment.

The successful completion of the Optimization and Design Phase, and the near completion of the Fabrication and Assembly Phase attests to the success of adapting the Edgewood Arsenal concepts and the design of the new parts. The only design uncertainty remaining is the adequacy of the new thermal insulation system used for the case. Edgewood Arsenal personnel approved the proposed new insulation system, which consists of an outer and an inner aluminum shell with the interspace completely filled with poured foaming-plastic insulation. Edgewood Arsenal's previous experience with some similar insulating systems gave reason to believe that this execution would prove adequate. However, tests of its adequacy must await the first completely assembled instrument, which will be subjected to the desired temperature range of  $-40^{\circ}$  to  $120^{\circ}\text{F}$ . In the unlikely event that the insulation proves inadequate, it may be necessary temporarily to restrict the low ambient-temperature limit range for operation of the three prototypes until the insulation can be improved or the case heating increased after the first limited field test. It is understood that the first field testing will not include extreme ambient conditions, so the ambient range limitation, if required, would not preclude obtaining the desired-field-test results.

Procurement of commercial components on the required time schedule has proved to be quite difficult. Edgewood Arsenal has alleviated the problem to a considerable extent by furnishing some components which could not be purchased quickly. However, substantial expediting effort on the part of Leeds & Northrup Company has been required to obtain those components which were not available from Edgewood Arsenal. This effort has been successful, and instrument assembly is proceeding on schedule with no delays expected from commercial component shortages.

### 1.3 Project Status

Phase One, Optimization and Design, was completed during August. Phase Two, Fabrication and Assembly, was started about midway through the Optimization and Design Phase. Fabrication is complete, and assembly, now in progress, will be completed in September. The Test Evaluation Phase will occupy the remainder of September and October, up to the shipment date.

It is not planned that the Final Report be completed by the shipment date. Rather, it will be prepared following the limited field tests by Edgewood Arsenal, and submitted at the end of January 1977.

## 2. EXPERIMENTAL RESULTS

When the parts for one electrochemical cell were available, they were assembled and initial performance testing was begun. The sample gas heater and controlling thermistor were not included in the cell assembly, necessitating the closure of these lead-in ports. Initially the holes were closed with plastic tape placed on the outer surface of the cell. This proved insufficient to prevent significant leakage, so the holes were plugged with silicone rubber sealant. Leakage was no longer evident.

The cell, pumps, flowmeters, electronics, etc. were assembled as shown schematically in figure 1. Room air was passed through the cell at 2.0 l/min. and 0.1M tris buffer with 0.125 mM butyrlthiocholine iodide was pumped into the reagent inlet port. The anode was operated at a controlled potential 0.5 volts positive of the silver wire (Ag/AgI) reference electrode. The output signal indicating the current flow at the anode was displayed on a strip chart recorder.

A plain polyurethane foam pad was inserted in the cell and the system activated. Initially an extremely high and erratic current was observed. It was observed that the current fluctuations corresponded to large pulsations in the inlet gas flow rate. Every 4-7 seconds the gas flow would decrease markedly, momentarily stopping altogether. Upon inspection of the cell flow passages, it was discovered that silicone rubber sealant had intruded into the inlet port when assembled. Figure 2a shows the initial design and assembly method of this portion of the cell, wherein silicone rubber sealant was coated on the interfacing surfaces of the cell parts before assembly, the parts then being mated, held with screws and the rubber cured. Significant sealant entered the port, restricting fluid flow such that slugs of reagent solution would momentarily block gas passage during operation.

A collar was added to the cell design as shown in figure 2b, effectively preventing intrusion of the sealant during assembly and curing. Neither obstruction of the passages nor flow irregularities have been observed with the modified cell design.

The modified cell, when initially operated with a blank foam pad, exhibited a current of 100-150  $\mu$ amps, unexpectedly high compared to the 1.0-1.5  $\mu$ amps observed with earlier prototypes operated in the same manner. Scanning the anode vs. silver wire reference potential while monitoring






Figure 1. Schematic of Test System




Figure 2a. Original Design Showing Area of Sealant Rubber Intrusion




Figure 2b. Collar Added to Design to Prevent Sealant Intrusion



the current showed a typical current-voltage curve. However, there was an apparent displacement of the curve by +0.2 volts, indicating that the silver wire reference was not at the proper potential. This was confirmed by measuring the silver wire potential versus a standard calomel electrode with a pH meter. Whereas the silver wire in this system should be 0.15 volt negative of the calomel reference electrode, it was in fact 0.05 volts more positive.

A new supply of silver wire (99.9%) was obtained, the wire abraided as previously, washed, and assembled into a cell. Unlike the earlier case, the silver was then anodized briefly in situ using the internal cathode of the cell as the counter electrode. The potential of the new silver reference measured -0.15 volts versus calomel and the shift observed in the scan was, of course, corrected. The high current observed previously with a blank pad was attributable to iodide oxidation caused by the malfunctioning reference electrode.

When activated, the cell with its new reference wire behaved as expected. The current with a blank pad was initially 1.5  $\mu$ amperes, decaying to 0.9  $\mu$ amperes in the first 25 minutes of operation, and to 0.6  $\mu$ amperes after 16 hours. With a starch entrapped enzyme pad, the current was initially 20  $\mu$ amperes after 8 hours. This performance is typical of that previously observed with earlier prototype cells and starch-entrapped enzyme pads.

Having verified satisfactory performance of the cell with both active enzyme and blank pads, the latter simulating the limiting case of deactivation with anticholinesterase agent, further manufacture of additional cells and alarm components was continued according to schedule. No experimental evidence indicates problems which would jeopardize the achievement of the contract objective on time.

3.            FURTHER WORK

The additional work to be completed under this contract includes the following:

- (a) Final assembly of three enzyme alarm instruments.
- (b) Laboratory testing of the assembled alarms.
- (c) Such modifications as may be indicated necessary by the testing.
- (d) Shipment of three enzyme alarms to Edgewood Arsenal for limited field testing.
- (e) Any modifications agreed upon as a result of the limited field tests.
- (f) Preparation, submission for approval, and publication of the Project Final Report.

### DISTRIBUTION LIST

<u>Recipient</u>	<u>Copies</u>
Administrator Defense Documentation Center Attn: Accessions Division Cameron Station Alexandria, VA 22314	12
Commander Edgewood Arsenal Attn: SAREA-DE-DDA/A. W. Davis Defense Systems Division, DDE Aberdeen Proving Ground, MD 21010	30
<u>Addressee</u>	
Technical Director, Attn: SAREA-TD	
Director of Dev & Engr. Attn: SAREA-DE (1)	
Dev & Engr Dir, Attn: SAREA-DE-DD (1)	
Dev & Engr Dir, Attn: SAREA-DE-DDR (1)	
Dev & Engr Dir, Attn: SAREA-DE-DDK (1)	
Dev & Engr Dir, Attn: SAREA-DE-DDA (RECORD COPY) (1)	
Dev & Engr Dir, Attn: SAREA-DE-DB/Mr. Ira Abelow (1)	
Contract Project Officer (9)	
Director of Tech Spt, Attn: SAREA-TS-L (Bldg. E3330) (3)	
Director of Tech Spt, Attn: SAREA-TS-E (1)	
Director of Tech Spt, Attn: SAREA-TS-R (1)	
Director of Cml Lab, Attn: SAREA-CL-PD/Dr. Epstein (1)	
Director of Cml Lab, Attn: SAREA-CL-CA/Mr. Sass (1)	
Commander, US Army Materiel Command, Attn: AMCRD-DC, Washington, DC 20315 (1)	
Commander, US Army Armament Command, Attn: DRSAR-RDM, Rock Island, IL 61201 (1)	
Commander, US Army Armament Command, Attn: DRSAR-RDT, Rock Island, IL 61201 (1)	
CO, Desert Test Center: STEDP-PA-RA(D) Dugway Proving Ground, UT 84022 (1)	
Commander, Naval Ships Command, Attn: Code 035-4 Washington, DC 20390 (1)	
Commander, Naval Weapons Laboratory, Attn: Code FC Dahlgren, VA 22448 (1)	
The Bendix Corporation, Environmental Science Division Attn: Dr. F. Davey, 1400 Taylor Avenue Baltimore, MD 21204 (1)	